

General Environmental Incident Summary

Incident: 3923 **Date/Time Notice:** 9/30/2015 1445 **DEM Incident No:**

Responsible Party: NDDOT

Date Incident: 9/29/2015 **Time Incident:** 1000 **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 98 **Sec:** 18 **Qtr:**

Lat: 47.80457 **Long:** -103.26220 **Method:** Interpolation from map

Location Description: Southwest quadrant of Hwy 23 and Business Hwy 23 in Watford City. Site is adjacent to the north of the County Fairgrounds, northwest of the airport, and adjacent to the south of Hwy 23, with commercial development to the north.

Submitted By: Kali Anderson

Affiliation: Braun Intertec

Address: 200 45th Sreet South, Suite

City: Fargo

State: ND

Zip: 58103

Received By:

Contact Person: Jason Peterson
PO Box 698
Williston, ND 58802

Distance Nearest Occupied Building: 200 Feet

Release Contained: No

Type of Incident: Excavation during roadway expansion

Description of Released Contaminant: Assumed hydrocarbon impacted soil

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Former filling station stated to have been located at this site. Impacts are assumed to be associated with former filling station (status of possible USTs unknown at this time).

Risk Evaluation:

None.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Impacted soil has been identified onsite; field PID screening has indicated organic vapors between approximately 200 ppm and 2,600 ppm. Impacts to groundwater unknown at this point.

Action Taken or Planned:

Impacted soils have begun to be excavated and are currently stockpiled onsite.

Wastes Disposal Location:

Agencies Involved: Local Emergency Manager

Updates

Date: 10/2/2015 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Suess, Bill

Updated Volume:

Notes:

Incident is most likely part of an historic site under the UST program.